Main data for Memory relays

Type	Symbol	Description	Connection (1)	Weight kg	Order code
Complete with sub-base PZU-B12 		With priority reset signal and visula indication With manual override	Ø4 mm Swivel push-in	0,19	**PLM-A12 ***
Without sub-base For sub-base PZU-B12 		With priority reset signal and visulal indication With manual override		0,14	**PLM-A10 ***
		Without manual override		0,13	**PLM-B10**

Main data for Amplifier relays

Type	Symbol	Description	Connection (1)	Weight kg	Order code
Complete with sub-base PZU-B12 		This relay is used to amplify the low pressure signal provided by a fluidic proximity sensor to a useable level With manual override	Ø4 mm Swivel push-in	0,18	**PRD-A12 ***
Without sub-base For sub-base PZU-B12 		This relay is used to amplify the low pressure signal provided by a fluidic proximity sensor to a useable level With manual override		0,13	**PRD-A10 ***

Main data for Sensor relays

Type	Symbol	Description	Connection (1)	Weight kg	Order code
Complete with sub-base PZU-A12 PRF-A12 * 		This relay is used to provide a supply to a bleed sensor and to generate a pneumatic signal equal to its supply pressure	Ø4 mm Swivel push-in	0,07	
Without sub-base For sub-base PZU-A12 or PZU-C12		This relay is used to provide a supply to a bleed sensor and to generate a pneumatic signal equal to its supply pressure		0,03	**PRF-A10 ***

* ATEX version available Order code example : **PLM-A12-EX**

(1) For other type of connections contact your Technical Sales Department

KOVAZ.cz